

NOTE: If threaded stud is required, replacement cylinder is no longer available.

